

Illustrated Parts List - IPL Update



Product Name(s)

H545

Description of change

1. Piston, assy (D43) : 577 04 70-06 was 577 04 70-02. Piston profile and ovality have been changed to minimize piston seizures.
2. Cylinder,assy with piston 577 76 47-06 was 577 76 47-04. Widened exhaust port. Machined groove added for reduced carbon build up in exhaust port.
3. Igniton Module 581 72 37-02 (Rv44) was 581 72 37-01 (Rv40).

Software updated:

We have changed the Ignition module to secure spark at idling and high speed.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20154200217	
s/n 20153500001	Valid for Ignition Module 581 72 37-02.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder - Piston	8	577 04 70-06	Piston,assy	577 04 70-02	
Cylinder - Piston	7	577 76 47-06	Cylinder,assy	577 76 47-04	
Ignition System	1	581 72 37-02	Ignition Module	581 72 37-01	