

Illustrated Parts List - IPL Update



Product Name(s)

H545

Description of change

1. Due to sealing problem and mounting problem we introduce a new Carburettor kit on **545**.
2. A new Flange.
3. A new Support sleeve.
4. Due to sealing problem: Cylinder,assy with piston, 577 76 47-04 was 577 76 47-02.

Comments

1. 587 08 48-01 => Carburettor,kit_AT7 + Support sleeve + Instruction.
2. 523 06 40-02 => Flange.
3. 585 19 50-01 => Support sleeve.

All changes are fully interchangeable.

Introduced from

Serial number / Date	Remark
s/n 20143800001	New Carburettor,kit .
s/n 20143800001	New Flange
s/n 20143800001	New Support sleeve .
s/n 20144100001	Valid for cylinder,assy – with piston, 577 76 47-04.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburettor Details	1	587 08 48-01	Carburettor,kit	584 97 38-01	
Carburettor & Air filter	10	587 08 48-01	Carburettor,kit	584 97 38-01	
Carburettor & Air filter	12	523 06 40-02	Flange	523 06 40-01	
Carburettor & Air filter	21	585 19 50-01	Support sleeve		
Cylinder piston	7	577 76 47-04	Cylinder,assy	577 76 47-02	