

Illustrated Parts List - IPL Update



Product Name(s)

576 XP, 576 XP EPA

Description of change

1 Screw IHSCFM 503 20 74-30: Replaced
2 Screw IHSCFM 503 20 74-30: Replaced

Comments

Following updated are fully interchangeable

Introduced from

Serial number / Date	Remark
2014-12-18	
2014-12-18	

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Crankcase	18	503 20 07-80	Screw IHSCFM	503 20 74-30	
Crankcase	22	503 20 07-80	Screw IHSCFM	503 20 74-30	