

Illustrated Parts List - IPL Update



Product Name(s)

H545

Description of change

1. New improved Fuel tank ventilation 501 15 29-01 added on tank 577 79 02-03. Tank ventilation improved regarding higher opening pressure.
2. A New Air filter, 522 67 54-07 has been introduced. This air filter has a new filter fabric with 25 µm. The new filter has an orange color.
The filter has replaced the 44 µm filter on PNC:s 545: 966 64 85, 966 64 86, 966 64 91 and 966 64 92. 44 µm filter remains as spare part.
3. New Tank cap assy and gasket number due to change of supplier.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20163500361	Valid for new Fuel Tank ventilation 501 15 29-01.
s/n 20164300653	Valid for Air filter 522 67 54-07.
s/n 20164300001	Valid for Tank cap assy. and gasket.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Fuel tank	5	501 15 29-01	Tank vent assy	537 35 95-01	
Crankcase	26	577 87 86-03	Tank cap, assy	577 87 86-01	
	27	589 24 13-01	Gasket	505 41 10-01	
Carburetor & Air filter	1	522 67 54-07	Air filter		New spare part.