

Illustrated Parts List - IPL Update



Husqvarna
Group

2014-12

Product Name(s)

H550XP/550XPG

Description of change

Ignition module,assy 581 72 36-02 (Rv.44) was 581 72 36-01 (Rv.40).
(Ignition module 581 61 72-02 (Rv.44) was 581 61 72-01 (Rv.40)).

Software updated:
We have changed the Ignition module to secure spark at idling and high speed.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
20144700193	Valid for ignition module,assy 581 72 36-02

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Ignition system	1	581 72 36-02	Ignition module,assy	581 72 36-01	