

# Illustrated Parts List - IPL Update



Product Name(s)

**H550XP/XPG**

Description of change

1. New Carburetor, kit AT-12 587 08 48-06 added. Improved acceleration and idle stability.
2. New Fuel hose 577 50 41-01 is 26 mm shorter than old 573 99 35-03 to fit new connection on Carburetor AT-12.
3. Choke control changed to secure correct assembly.

Comments

This update is fully exchangeable.

Introduced from


Serial number / Date	Remark
s/n 20161000481	Carburetor AT-12.
s/n 20161000481	Valid for Fuel hose 577 50 41-01.
s/n 20153900097	Valid for Choke control 510 01 72-02.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Carburetor & details	1	587 08 48-06	Carburettor kit	587 08 48-02	With new Fuel hose 577 50 41-01.
Carburetor & air filter	4	510 01 72-02	Choke control	510 01 72-01	
	10	587 08 48-06	Carburettor kit	587 08 48-02	With new Fuel hose 577 50 41-01.
Fuel tank	24	577 50 41-01	Fuel hose		

## 2. Fuel hose, Instruction.

When you don't want to change to the new fuel hose included in kit, Carburetor.  
Cut your old hose like this:




537 99 35-03

3. Choke control.



510 01 72-02



510 01 72-01

