

Illustrated Parts List - IPL Update



Product Name(s)

576 XP AUTO TUNE

Description of change

1 DECOMPRESSION VALVE: Improved.

Comments

Introduced from

Serial number / Date	Remark
20140800001/2014-02-18	DECOMPRESSION VALVE 584 28 87-01

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder Piston	3	584 28 87-01	DECOMPRES SION VALVE	537 29 44-01	