

Illustrated Parts List - IPL Update



Product Name(s)

576 XP AUTO TUNE

Description of change

1 CLUTCH DRUM: Replaced
2 CLUTCH DRUM: Replaced

Comments

Fully interchangeable

Introduced from

Serial number / Date	Remark
2014-10-29	CLUTCH DRUM ventilation holes excluded
2014-10-29	CLUTCH DRUM ventilation holes excluded

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Clutch & Oil pump	1	504 54 72-02	CLUTCH DRUM	502 44 04-02	
Clutch & Oil pump	1	504 54 72-03	CLUTCH DRUM	502 44 04-03	