

Illustrated Parts List - IPL Update



Product Name(s)

135E

Description of change

1. Clutch assy. corrected.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
2015 – 02 - 18	Clutch assy corrected.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Clutch & Oilpump	1	530 01 49-49	Clutch assy	544 87 12-01	Remain as spare part for other products.
Clutch & Oilpump	2	530 09 41-88	Clutch spring	502 08 03-01	Remain as spare part for other products.
Clutch & Oilpump	9	530 01 56-01	Washer		

1. Clutch assy.



530 01 49-49



544 87 12-01




530 09 41-88



502 08 03-01



Illustrated Parts List - IPL Update



530 01 56-01 (Added)